



Important Notice

Before Upgrading to Firmware V4.00

Applied to

GV-AS / EV Controllers Firmware V4.00

Important Notice

The upgrade adds support for assigning up to **four Access Groups** to a single card/vehicle per Device Group.

Read carefully before proceeding with the upgrade:

1. **System Compatibility:** Firmware V4.00 for GV-AS21 / 41 / 81 series controllers requires GV-ASManager V6.4.0.
2. **Required Upgrade Sequence:** Upgrading to Firmware V4.00 without updating GV-ASManager to V6.4.0 will cause the system to fail to log access events.
3. **Card Capacity Reduction:** Upgrading to Firmware V4.00 / Software V6.4.0 reduces total card capacity from 100,000 to 40,000. Verify that your system has 40,000 or fewer active card IDs before upgrading; **any card ID beyond 40,000 limit will be removed.**

[Download Firmware V4.00]

GV-AS210 / 2110 / 2120 V4.00:

https://dlcdn.geovision.com.tw/Firmware/AccessControl/AS210_2110_2120/AS210_V400_20261005.zip

GV-AS410 / 4110 / 4111 V4.00:

https://dlcdn.geovision.com.tw/Firmware/AccessControl/AS410_4110_4111/AS410_V400_20261002.zip

GV-AS810 / 8110 / 8111 V4.00:

https://dlcdn.geovision.com.tw/Firmware/AccessControl/AS810_8110_8111/AS810_V400_20261002.zip

[Download Software V6.4.0]

GV-ASManager V6.4: https://dlcdn.geovision.com.tw/Software/Paid/GV-ASManager_V6.4.0.zip